



LAYERABLE WARMTH
STRETCH
FLATLOCK SEAMS FOR COMFORT
REFLECTIVE DETAILS

- 95/5 poly/spandex jersey
- Reflective OGIO Endurance heat transfer label for tag-free comfort
- Zip-through cadet collar
- Reflective O heat transfer at back neck
- Reflective welding around zippered chest pocket
- Tonal embossed O pattern at side panels
- Lower front zippered pockets
- Set-in sleeves with shaped cuffs
- Reflective O Endurance heat transfer at left sleeve
- Slight drop tail hem
- Reflective O heat transfer at front right hem




front



back

HOW TO MEASURE






CHEST
With arms down at sides, measure around the upper body, under arms and over the fullest part of the chest.

SIZE CHART

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	32-34	35-37	38-40	41-43	44-46	47-49	50-53	54-57

COLOR INFORMATION

		
Blacktop PMS NTR BLACK	Electric Blue PMS 7686 C	Gear Grey PMS 7540 C

[View PDF](#) | [Print](#) | [Email](#)

PRODUCT MEASUREMENTS

	XS	S	M	L	XL	2XL	3XL	4XL
Chest	18 1/4	19 3/4	21 1/4	22 3/4	24 1/4	25 3/4	27 3/4	29 3/4
Body Length at Back	26 1/4	27 1/4	28 3/8	29 1/2	30 5/8	31 3/4	32 3/8	33
Sleeve Length	35 1/4	36	36 3/4	37 1/2	38 1/4	39	39 3/4	40 1/2

CHEST
Measured across the chest one inch below armhole when laid flat.

BODY LENGTH AT BACK
Measured from high point shoulder to finished hem at back.

SLEEVE LENGTH
Start at center of neck and measure down shoulder, down sleeve to hem.